

TOP PIVOT HEADER PORTION

DO NOT SCALE

NOTE: If door is inset $\frac{1}{8}$ " from lavatory side, no special latch strike is normally required.

